







TEST REPORT

The report shall not be reproduced without written approval from Intertek
The results relate only to the item tested.

Report No.: BKKH210

Test conducted

Test result:

1.Determination of microbial effectiveness of ozone generator in Air Based on customer's requirement.

1.1 Total Aerobic plate count

nic Oz	The number of microorganisms before process the ozone generator (CFU/m³) (A)	The number of microorganisms after process the ozone generator (CFU/m³) (B)	% Reduction
Total aerobic plate count	830	145	82.50%

1.2 Total Yeast & Mold count

Ozonic	The number of microorganisms before process the ozone generator (CFU/m³) (A)	The number of microorganisms after process the ozone generator (CFU/m³) (B)	% Reduction
Total Yeast & Mold count	535	140	73.80%

1.3 Escherichia coli ATCC 8739 count

nic Oz	20	The number of microorganisms did not process the ozone generator (CFU/plate) (A)	The number of microorganisms after process the ozone generator (CFU/plate) (B)	% Reduction
Escherichia coli ATCC 8739 count	#1	208	1	99.50%
	#2	212	2	99.10%

Remark:

CFU

= Colony forming unit

% Reduction

= 100 (A-B)/A

Testing period: November 18, 2021 to December 03, 2021

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: http://www.intertek.com/terms/. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk. This report shall not be reproduced, except in full.

Intertek Testing Services (Thailand) Ltd.

1285/5 Prachachuen Road, Wong-Sawang, Bangsue, Bangkok 10800 Thailand Tel + 662 765 2999 Fax + 662 765 2936 www.intertek.com

